



# Components Supplied in the Kit

Written By: REA



## INTRODUCTION

Supplied Components:

### Qty Name

- 1 Hitec HS-646WP Servo
- 17 M3 Brass threaded insert
- 17 M3x8mm Stainless Socket Head Cap Screw
- 2 M3x6mm Stainless Grub Screw
- 1 4mm Brass Rod
- 1 24T C1 Spline Gear
- 1 4mm Bore 32 Pitch, 16T Shaft Mount Pinion Gear

This guide outlines the parts that come in the kit that are required for the Fore Cap Assembly. Find these parts and put them aside ready for the assembly guides for the Fore Cap.

## Step 1 — Hitec Servo



- 1 x Hitec HS646WP servos are required for the Fore Cap Assembly

## Step 2 — M3 Threaded Insert



- 17 x M3 Threaded insert are required for the Fore Cap Assembly

### Step 3 — M3 x 8mm Stainless Socket Head Cap Screw




- 17 x M3 Stainless Socket Head Cap Screws are required for the Fore Cap Assembly

### Step 4 — M3x6mm Stainless Set Screw



- 2 x M3 x 6mm set screws required for the roe cap assembly

## Step 5 — 4mm Brass Rod



- 1 x 4mm Brass rod's are required for the Fore Cap Assembly

## Step 6 — 24T C1 Spline Gear



- 1 x 24T C1 Spline Gear is required for the Fore Cap Assembly.

## Step 7 — 4mm Bore 16T Shaft Mount Pinion Gear



- 1 x 4mm Bore 16T Shaft Mount Pinion Gear is required for the Fore Cap Assembly.